Gearbox

Axle Combi



VEHICLE INSPECTION REPORT

Vehicle

Colour

VIN

PE13HLH

HYDROSTATIC

4WD

TORO LT3340

Inspection

Year Mileage

| | | VAT | Plus VAT Present | | |
|-----------|------------|-----------|---------------------|------------|----------------|
| | | V5 | | | |
| Details | | | | | |
| Reg. date | 01/04/2013 | Fuel Type | DIESEL | Body Style | Mowing Machine |

RED

30657313000026

2013

4,807 Hours Not

Warranted

| CYLINDER DECKS | |
|----------------|--|
| Tyres NSF | |
| NSF | |
| NSR | |
| OSF OSR | |
| OSR | |
| Spare | |

Photos













